

SERVICE SOLUTIONS // HOW TO

HOW TO PERFORM A RUNNING-IN OF NEW SAW BLADES ON THE RSLL 108 - 109 - 110

Following procedure must be used with every new blade

1. Ensure that the blades are whet on the back side on the cutting edge
2. Place whetstone plane with the backside of the blade

Day 1:



- The first hour once every 10 minutes
- The next 2 hours once every 15 minutes
- The following 6 hours once every 30 minutes

Day 2-4:

- Whetting is recommended 3-4 times a day

Afterwards:

- Whet minimum ones a day



Whetstone - part no.: 4600363569

AfterSales_V1-0_2022_EN

CONTACT

Central/Eastern Europe
+49 252 185 070
service.de@frontmatec.com

Northern Europe, Kolding
+45 36 999 099
service.kol.dk@frontmatec.com

Northern Europe, Tandslet
+48 227 345 551
service.tan.dk@frontmatec.com

Southern Europe
+34 932 643 800
service.es@frontmatec.com

Western Europe
+31 886 294 000
service.nl@frontmatec.com