

## Spare parts packages



## Every single spare part counts

### Spare parts play a key role

In order to ensure maximized up-time, daily maintenance has become even more important, as this is of utmost importance to achieve a smooth operation.

We know, that every little spare part counts, and by having the right spares in stock, you avoid that even the smallest spare part ends up being the most expensive one.

With tailored spare part packages covering service, wear and tear parts you can ensure the high level of daily service and maintenance needed for an efficient production and continuous increased profit and yield.

We can assist you with everything from the basic spare part package, supporting commissioning and light maintenance, to the recommended spare part package needed to maintain consistent high performance of your equipment, and with that, a profitable production.

Please do not hesitate to contact your local After Sales department. Our experienced sales engineers are ready to provide you with guidance in regards to your tailored spare part package, ensuring maximum uptime and keeping your equipment in original great shape.

### Value for you!

- Low mean time to repair
- Maximize yield
- Secure up-time on daily maintenance and repairs
- High and consistent performance of your equipment
- Extended life-time of your equipment
- Optimizes labor costs

## Contact

Central/Eastern Europe  
Phone: +49 252 185 070  
E-mail: [as.ce@frontmatec.com](mailto:as.ce@frontmatec.com)

Central/Eastern Europe, Poland  
Phone: +48 227 345 551  
E-mail: [as.ce@frontmatec.com](mailto:as.ce@frontmatec.com)

Northern Europe  
Phone: +45 36 999 099  
E-mail: [as.ne@frontmatec.com](mailto:as.ne@frontmatec.com)

Southern Europe  
Phone: +34 932 643 800  
E-mail: [as.se@frontmatec.com](mailto:as.se@frontmatec.com)

Russia  
Phone: +7 495 424 9559  
E-mail: [as.ru@frontmatec.com](mailto:as.ru@frontmatec.com)

Western Europe  
Phone: +31 886 294 000  
E-mail: [as.we@frontmatec.com](mailto:as.we@frontmatec.com)